



**Kongsberg Maritime AS  
Sensors and Robotics  
Strandpromenaden 50  
N-3183 Horten  
NORWAY**

**P.O. Box 111  
N-3191 Horten**

Our ref.: Mr. Reidar Syversen  
Your ref.: Mr. Karol Jan Jankowski

**Att. Mr. Karol Jan Jankowski**

**Oslo, 2020-08-26**

**ATEX surveillance audit carried out by Nemko AS**

Reference is made to the audit of your factory 2020-06-18, and the audit report from the same date.  
Nemko Order No. 400923.

**Nemko AS, notified body number 0470 for Annex IV/VII hereby confirms that the  
ATEX QA Notification with ref. Nemko 10ATEX4142Q is maintained and valid.**

The next audit will be carried out according to schedule. All inspections will follow NEK ISO/IEC 80079-34:2018 and Dir. 2014/34/EU.

However, we do reserve the right to come on occasional visits that will be charged accordingly, if deemed necessary for safety reasons (Ref. Dir. 2014/34/EU A:IV / A:VII, Section 4.4).

In any case, the certification body issuing the product certificate must be informed about possible safety related product- or component changes to certified products.

Any change of the name, address or contact person / Ex responsible person of the manufacturer / factory(-ies) shall be informed to Nemko AS.

If an unsafe, non-conforming product has been supplied to a customer, the manufacturer shall, in writing, inform its customer and the notified body responsible for the quality system notification.

As we are looking forward to our continuous cooperation we remain.

Yours sincerely  
Nemko AS

Reidar Syversen  
Senior Engineer; Lead Auditor ATEX & IECEX  
Factory Inspection Department  
E-mail address: [reidar.syversen@nemko.com](mailto:reidar.syversen@nemko.com)